

Bridgeport Elementary

Location Number	Description	Sample #	Sample Date	Results	Remediation	Retest Sample #	Retest Date	Retest Results
1	Kitchen Sink East Wall	BP-1	4/8/16	.0082 mg/L				
2	Kitchen Sink Right North Wall	BP-2	4/8/16	.0066 mg/L				
3	Kitchen Sink Center North Wall	BP-3	4/8/16	.0075 mg/L				
4	Kitchen Sink Left North Wall	BP-4	4/8/16	.0051 mg/L				
5	Kitchen Bath Hand Sink	BP2-5	9/28/16	.022 mg/L	Posted Non-Potable, Replace fixture, Retest			
6	Kitchen Custodial Sink	BP2-6	9/28/16	.033 mg/L	Posted Non-Potable, Replace fixture, Retest			
7	Room 125 Hand Sink	BP2-7	9/28/16	.023 mg/L	Posted Non-Potable, Replace fixture, Retest			
8	Room 126 Hand Sink	BP2-8	9/28/16	.0076 mg/L				
9	Main Entrance Water Fountain Right	BP-5	4/8/16	.0036 mg/L				
10	Main Entrance Water Fountain Left	BP-6	4/8/16	.0036 mg/L				
11	Boys Bath Hand Sink (Left)	BP2-11	9/28/16	<.0010 mg/L				
12	Girls Bath Hand Sink (Right)	BP2-12	9/28/16	<.0010 mg/L				
13	Main Office Hand Sink	BP-7	4/8/16	.0030 mg/L				
14	Principal Bath Hand Sink	BP2-14	9/28/16	.012 mg/L				
15	Room 102 Bath Hand Sink	BP2-15	9/28/16	.0036 mg/L				
16	Room 102 Hand Sink	BP2-16	9/28/16	.0038 mg/L				
17	Room 102 Water Fountain	BP-8	4/8/16	.0026 mg/L				
18	Room 108 Nurses Office Hand Sink	BP-9	4/8/16	.0043 mg/L				
19	Nurses Office Bath Hand Sink	BP2-19	9/28/16	<.0010 mg/L				
20	Room 104 Bath Hand Sink	BP2-20	9/28/16	.0054 mg/L				
21	Room 104 Hand Sink	BP2-21	9/28/16	.0028 mg/L				
22	Room 104 Water Fountain	BP-10	4/8/16	.0037 mg/L				
23	Fourth Grade Custodial Sink	BP2-23	9/28/16	.0055 mg/L				
24	Room 103 Bath Hand Sink	BP2-24	9/28/16	.0041 mg/L				
25	Room 103 Hand Sink	BP2-25	9/28/16	.0032 mg/L				
26	Room 103 Water Fountain	BP-11	4/8/16	.0040 mg/L				
27	Library Hand Sink	BP2-27	9/28/16	.0045 mg/L				
28	Library Bath Hand Sink	BP2-28	9/28/16	.0098 mg/L				
29	Library Hall Water Fountain	BP-12	4/8/16	.005 mg/L				
30	Room 130 Bath Hand Sink	BP2-30	9/28/16	.0049 mg/L				
31	Room 133 Bath Hand Sink	BP2-31	9/28/16	.0032 mg/L				
32	Room 133 Counter Hand Sink(Hallway)	BP2-32	9/28/16	.0010 mg/L				
33	Room 133 Counter Hand Sink (Window)	BP2-33	9/28/16	<.0010 mg/L				
34	Room 122/105 Bath Hand Sink	BP2-34	9/28/16	.020 mg/L	Posted Non-Potable, Replace fixture, Retest			
35	Room 105 Water Fountain	BP-14	4/8/16	.0028 mg/L				
36	Room 105 Hand Sink	BP2-36	9/28/16	.0039 mg/L				
37	Room 105/106 Bath Hand Sink	BP2-37	9/28/16	.0038 mg/L				
38	Room 134 Water Fountain	BP-13	4/8/16	.0030 mg/L				
39	Room 134 Hand Sink	BP2-39	9/28/16	.0037 mg/L				
40	Room 134/107 Bath Hand Sink	BP2-40	9/28/16	.0041 mg/L				
41	Room 107 Water Fountain	BP-15	4/8/16	.0049 mg/L				
42	Room 107 Hand Sink	BP2-42	9/28/16	.014 mg/L				
43	Room 107 Bath Hand Sink	BP2-43	9/28/16	.024 mg/L	Posted Non-Potable, Replace fixture, Retest			
44	Room 106 Water Fountain	BP-16	4/8/16	.0042 mg/L				
45	Room 106 Hand Sink	BP2-45	9/28/16	.026 mg/L	Posted Non-Potable, Replace fixture, Retest			
46	Room 106 Bath Hand Sink	BP2-46	9/28/16	.0040 mg/L				
47	Room 113 Hand Sink	BP2-47	9/28/16	.0016 mg/L				
48	Room 113 Water Fountain	BP-22	4/8/16	.0043 mg/L				
49	Room 114 Hand Sink	BP2-49	9/28/16	.0012 mg/L				
50	Room 114 Water Fountain	BP-20	4/8/16	.0017 mg/L				
51	Room 101 Hand Sink	BP-18	4/8/16	.0013 mg/L				
52	Room 101 Bath Hand Sink	BP2-52	9/28/16	.0018 mg/L				
53	Room 120 Bath Hand Sink	BP2-53	9/28/16	.0036 mg/L				
54	Room 120 Hand Sink	BP2-54	9/28/16	.0080 mg/L				
55	Room 120 Water Fountain	BP-17	4/8/16	.0031 mg/L				
56	Room 121 Water Fountain	BP-19	4/8/16	<.0010 mg/L				
57	Room 121 Hand Sink	BP2-57	9/28/16	<.0010 mg/L				
58	Room 128 Hand Sink	BP2-58	9/28/16	<.0010 mg/L				
59	Room 128 Water Fountain	BP-21	4/8/16	.0038 mg/L				
60	Room 119 Water Fountain	BP-23	4/8/16	<.0010 mg/L				
61	Room 119 Hand Sink	BP2-61	9/28/16	.015 mg/L	Posted Non-Potable, Replace fixture, Retest			
62	Room 112 Hand Sink	BP2-62	9/28/16	.0011 mg/L				
63	Room 112 Water Fountain	BP-25	4/8/16	.0031 mg/L				
64	Room 118 Water Fountain	BP-24	4/8/16	.0014 mg/L				
65	Room 118 Hand Sink	BP2-65	9/28/16	.0012 mg/L				
66	Room 117 Water Fountain	BP-26	4/8/16	.0021 mg/L				
67	Room 117 Hand Sink	BP2-67	9/28/16	.0011 mg/L				
68	Room 111 Hand Sink	BP2-68	9/28/16	.0079 mg/L				
69	Room 111 Water Fountain	BP-27	4/8/16	.0030 mg/L				
70	Room 116 Water Fountain	BP-28	4/8/16	<.0010 mg/L				
71	Room 116 Hand Sink	BP2-71	9/28/16	.0027 mg/L				
72	Room 110 Hand Sink	BP2-72	9/28/16	.0054 mg/L				
73	Room 110 Hot Water Supply	BP-29	4/8/16	.0068 mg/L				
74	Room 123 Hand Sink	BP2-74	9/28/16	.0084 mg/L				
75	Gym Hall Water Fountain	BP-31	4/8/16	.0040 mg/L				
76	Room 115 Hand Sink	BP2-76	9/28/16	.014 mg/L				
77	Room 115 Water Fountain	BP-32	4/8/16	.0040 mg/L				
78	Boys Locker Left Hand Sink	BP2-78	9/28/16	.018 mg/L	Posted Non-Potable, Replace fixture, Retest			
79	Boys Locker Right Hand Sink	BP2-79	9/28/16	.0045 mg/L				
80	Boys Locker Water Fountain	BP-33	4/8/16	.024 mg/L	Disconnected power and water supply to fountain. No longer in service.			
81	PE Office Hand Sink	BP2-81	9/28/16	.010 mg/L				
82	Room 109 Left Water Fountain	BP-35	4/8/16	.0058 mg/L				
83	Room 109 Hand Sink (Center)	BP2-83	9/28/16	.0016 mg/L				
84	Room 109 Right Water Fountain	BP-30	4/8/16	<.0010 mg/L				
85	Room 109 Hand Sink (Right)	BP2-85	9/28/16	.0036 mg/L				
86	Custodial Closet Sink	BP2-86	9/28/16	.0021 mg/L				
87	Girls Locker Left Hand Sink	BP2-87	9/28/16	.0077 mg/L				
88	Girls Locker Right Hand Sink	BP2-88	9/28/16	.018 mg/L	Posted Non-Potable, Replace fixture, Retest			
89	Girls Locker Water Fountain	BP-34	4/8/16	.014 mg/L	Disconnected power and water supply to fountain. No longer in service.			
90	Maint Office Custodial Sink	BP2-90	9/28/16	.0043 mg/L				

Bolivar Elementary

Location Number	Description	Sample #	Sample Date	Results	Remediation	Retest Sample #	Retest Date	Retest Results
1	Kitchen Wash Sink Left/North Wall	BO-4	4/8/16	<.0010 mg/L				
2	Kitchen Wash Sink Center/North Wall	BO-3	4/8/16	<.0010 mg/L				
3	Kitchen Wash Sink Right/North Wall	BO-2	4/8/16	<.0010 mg/L				
4	Kitchen Wash Sink East Wall	BO-1	4/8/16	.0014 mg/L				
5	Soup Kettle Supply	BO-5	4/8/16	.0012 mg/L				
6	Kitchen Bath Hand Sink	BO2-6	9/29/16	<.0010 mg/L				
7	Faculty Hand Sink	BO-6	4/8/16	<.0010 mg/L				
8	Faculty Bath Hand Sink	BO2-8	9/29/16	<.0010 mg/L				
9	Library Hand Sink	BO-7	4/8/16	.0015 mg/L				
10	Library Hall Custodial Sink	BO2-100	9/29/16	.13 mg/L	Posted Non-Potable, Replace fixture, Retest			
11	Room 176 Water Fountain	BO-8	4/8/16	<.0010 mg/L				
12	Room 176 Hand Sink	BO2-12	9/29/16	<.0010 mg/L				
13	Room 171 South Wall Hand Sink	BO2-13	9/29/16	<.0010 mg/L				
14	Room 171 Island Hand Sink (Hall)	BO2-14	9/29/16	.0040 mg/L				
15	Room 171 Island Hand Sink (Window)	BO2-15	9/29/16	.0051 mg/L				
16	Room 170 Hand Sink	BO2-16	9/29/16	<.0010 mg/L				
17	Room 170 Water Fountain	BO-9	4/8/16	<.0010 mg/L				
18	Room 114 Water Fountain	BO-10	4/8/16	<.0010 mg/L				
19	Room 114 Hand Sink	BO2-19	9/29/16	<.0010 mg/L				
20	Room 115 Hand Sink	BO2-20	9/29/16	<.0010 mg/L				
21	Room 115 Water Fountain	BO-11	4/8/16	<.0010 mg/L				
22	Second Grade Hall Custodial Sink	BO2-22	9/29/16	.0052 mg/L				
23	Room 132 Water Fountain	BO-12	4/8/16	<.0010 mg/L				
24	Room 132 Hand Sink	BO2-24	9/29/16	<.0010 mg/L				
25	Room 131 Water Fountain	BO-13	4/8/16	<.0010 mg/L				
26	Room 131 Hand Sink	BO2-26	9/29/16	<.0010 mg/L				
27	Room 130 Water Fountain	BO-14	4/8/16	<.0010 mg/L				
28	Room 130 Hand Sink	BO2-28	9/29/16	<.0010 mg/L				
29	Room 129 Water Fountain	BO-15	4/8/16	<.0010 mg/L				
30	Room 129 Hand Sink	BO2-30	9/29/16	.0078 mg/L				
31	Room 128 Water Fountain	BO-16	4/8/16	<.0010 mg/L				
32	Room 128 Hand Sink	BO2-32	9/29/16	<.0010 mg/L				
33	Room 127 Water Fountain	BO-17	4/8/16	<.0010 mg/L				
34	Room 127 Hand Sink	BO2-34	9/29/16	<.0010 mg/L				
35	Room 126 Water Fountain	BO-18	4/8/16	<.0010 mg/L				
36	Room 126 Hand Sink	BO2-36	9/29/16	<.0010 mg/L				
37	Room 125 Water Fountain	BO-19	4/8/16	<.0010 mg/L				
38	Room 125 Hand Sink	BO2-38	9/29/16	<.0010 mg/L				
39	Room 122 Hand Sink	BO2-39	9/29/16	.0018 mg/L				
40	Room 122 Water Fountain	BO-21	4/8/16	<.0010 mg/L				
41	Room 121 Water Fountain	BO-20	4/8/16	<.0010 mg/L				
42	Room 121 Hand Sink	BO2-42	9/29/16	.0014 mg/L				
43	Room 119 Water Fountain	BO-22	4/8/16	<.0010 mg/L				
44	Room 119 Hand Sink	BO2-44	9/29/16	<.0010 mg/L				
45	Room 120 Hand Sink	BO2-45	9/29/16	.0014 mg/L				
46	Room 120 Water Fountain	BO-23	4/8/16	<.0010 mg/L				
47	Room 116 Water Fountain	BO-24	4/8/16	<.0010 mg/L				
48	Room 116 Hand Sink	BO2-48	9/29/16	.0010 mg/L				
49	Room 118 Hand Sink	BO2-49	9/29/16	<.0010 mg/L				
50	Room 118 Water Fountain	BO-25	4/8/16	<.0010 mg/L				
51	Receiving Room Custodial Sink	BO2-51	9/29/16	<.0010 mg/L				
52	Room 134 Hand Sink	BO2-52	9/29/16	.0026 mg/L				
53	Cafeteria Bath Hand Sink	BO2-53	9/29/16	.0037 mg/L				
54	Cafeteria Water Fountain Right	BO-30	4/8/16	<.0010 mg/L				
55	Cafeteria Water Fountain Left	BO-31	4/8/16	<.0010 mg/L				
56	Girls Bathroom Left Hand Sink	BO2-56	9/29/16	<.0010 mg/L				
57	Girls Bathroom Center Hand Sink	BO2-57	9/29/16	<.0010 mg/L				
58	Girls Bathroom Right Hand Sink	BO2-58	9/29/16	<.0010 mg/L				
59	Boys Bathroom Right Hand Sink	BO2-59	9/29/16	<.0010 mg/L				
60	Boys Bathroom Center Hand Sink	BO2-60	9/29/16	<.0010 mg/L				
61	Boys Bathroom Left Hand Sink	BO2-61	9/29/16	<.0010 mg/L				
62	Main Entrance Water Fountain	BO-32	4/8/16	<.0010 mg/L				
63	Main Office Hand Sink	BO-33	4/8/16	<.0010 mg/L				
64	Main Office Hall Bath Hand Sink	BO2-64	9/29/16	<.0010 mg/L				
65	Nurses Office Hand Sink	BO-34	4/8/16	<.0010 mg/L				
66	Nurses Office Bath Hand Sink	BO2-66	9/29/16	<.0010 mg/L				
67	Kindergarten/First Hall Water Fountain	BO-35	4/8/16	<.0010 mg/L				
68	Coaches Office Bath Hand Sink	BO2-68	9/29/16	.0019 mg/L				
69	Kindergarten Hall Bath Hand Sink	BO2-69	9/29/16	.0012 mg/L				
70	Kindergarten Hall Custodial Sink	BO2-70	9/29/16	.0032 mh/L				
71	Room 100 Hand Sink	BO2-71	9/29/16	<.0010 mg/L				
72	Room 100 Water Fountain	BO-38	4/8/16	<.0010 mg/L				
73	Room 101 Hand Sink	BO2-73	9/29/16	<.0010 mg/L				
74	Room 104 Water Fountain	BO-39	4/8/16	<.0010 mg/L				
75	Room 104 Hand Sink	BO2-75	9/29/16	<.0010 mg/L				
76	Room 103 Hand Sink	BO2-76	9/29/16	.0014 mg/L				
77	Room 103 Water Fountain	BO-40	4/8/16	<.0010 mg/L				
78	Room 106 Water Fountain	BO-41	4/8/16	<.0010 mg/L				
79	Room 106 Hand Sink	BO2-79	9/29/16	<.0010 mg/L				
80	Room 105 Hand Sink	BO2-80	9/29/16	.0012 mg/L				
81	Room 105 Water Fountain	BO-42	4/8/16	<.0010 mg/L				
82	Room 108 Hand Sink Right	BO-43	4/8/16	<.0010 mg/L				
83	Room 108 Hand Sink Left	BO-44	4/8/16	<.0010 mg/L				
84	Rom 107 Hand Sink	BO2-84	9/29/16	.0027 mg/L				
85	Room 107 Water Fountain	BO-45	4/8/16	<.0010 mg/L				
86	Room 110 Hand Sink Left	BO-47	4/8/16	.0023 mg/L				
87	Room 110 Hand Sink Right	BO-46	4/8/16	<.0010 mg/L				
88	Room 109 Hand Sink Left	BO-49	4/8/16	.0011 mg/L				
89	Room 109 Hand Sink Right	BO-48	4/8/16	.0015 mg/L				
90	Room 112 Hand Sink Right	BO-51	4/8/16	.0011 mg/L				
91	Room 112 Hand Sink Left	BO-52	4/8/16	.0033 mg/L				
92	Room 111 Hand Sink Right	BO-53	4/8/16	.0013 mg/L				
93	Room 111 Hand Sink Left	BO-54	4/8/16	.0012 mg/L				
94	Kindergarten Hall Water Fountain	BO-50	4/8/16	<.0010 mg/L				
95	Multipurpose Hall Water Fountain Right	BO-36	4/8/16	<.0010 mg/L				
96	Multipurpose Hall Water Fountain Left	BO-37	4/8/16	<.0010 mg/L				
97	Boys Bathroom Hand Sink	BO2-97	9/29/16	<.0010 mg/L				
98	Girls Bathroom Hand Sink	BO2-98	9/29/16	<.0010 mg/L				
99	Coaches Office Bath Hand Sink	BO2-99	9/29/16	.0024 mg/L				
100	Receiving Area Outside Hose Bib	BO2-100	9/29/16	.0035 mg/L				

Middle School

Location Number	Description	Sample #	Sample Date	Results	Remediation	Retest Sample #	Retest Date	Retest Results
1	Kitchen Custodial Sink	MS2-1	9/27/16	.0013 mg/L				
2	Ice Maker	MS2-2	9/27/16	.014 mg/L				
3	Kitchen Hand Sink	MS-32	4/12/16	.0012 mg/L				
4	Cook Sink North	MS-1	4/12/16	.0027 mg/L				
5	Cook Sink South	MS-2	4/12/16	.0025 mg/L				
6	Cook Sink Left	MS-5	4/12/16	.0017 mg/L				
7	Cook Sink Right	MS-6	4/12/16	.0024 mg/L				
8	Kettle Nearest Office	MS-3	4/12/16	.0027 mg/L				
9	Kettle Nearest Dishwasher	MS-4	4/12/16	<.0010 mg/L				
10	Cook Sink (Island)	MS-7	4/12/16	.0023 mg/L				
11	Kitchen Hand Sink	MS-8	4/12/16	<.0010 mg/L				
12	Food Service Bath Hand Sink	MS2-12	9/27/16	<.0010 mg/L				
13	Faculty Room Sink	MS-10	4/12/16	.0011 mg/L				
14	Cafeteria Water Fountain	MS-9	4/12/16	<.0010 mg/L				
15	Boys Bath Hand Sink Left	MS2-15	9/27/16	.0013 mg/L				
16	Boys Bath Hand Sink Right	MS2-16	9/27/16	.0024 mg/L				
17	Girls Bath Hand Sink Left	MS2-17	9/27/16	.0016 mg/L				
18	Girls Bath Hand Sink Right	MS2-18	9/27/16	<.0010 mg/L				
19	Cafeteria Hall Water Fountain	MS-11	4/12/16	<.0010 mg/L				
20	Womens Bath Hand Sink	MS2-20	9/27/16	.0023 mg/L				
21	Mens Bath Hand Sink	MS2-21	9/27/16	.0026 mg/L				
22	Band Practice Room Hand Sink	MS2-22	9/27/16	.0011 mg/L				
23	Gym Hall Water Fountain North	MS-12	4/12/16	<.0010 mg/L				
24	Boys Locker Hand Sink Right	MS2-24	9/27/16	<.0010 mg/L				
25	Boys Locker Hand Sink Left	MS2-25	9/27/16	.0039 mg/L				
26	Mens PE Office Bath Hand Sink	MS2-26	9/27/16	.0011 mg/L				
27	Gym Custodial Sink	MS2-27	9/27/16	.0024 mg/L				
28	Gym Hall Water Fountain South	MS-13	4/12/16	<.0010 mg/L				
29	Girls Locker Hand Sink Left	MS2-29	9/27/16	.0019 mg/L				
30	Girls Locker Hand Sink Right	MS2-30	9/27/16	<.0010 mg/L				
31	Womens PE Office Bath Hand Sink	MS2-31	9/27/16	.0014 mg/L				
32	Room 114 Hand Sink North	MS-17	4/12/16	.019 mg/L	Replaced Faucet, Supply Lines, fittings, and solder to main	10/4/2016	MS3-32	.0061 mg/L
33	Room 114 Hand Sink Right	MS-14	4/12/16	.0039 mg/L				
34	Room 114 Hand Sink Left	MS-15	4/12/16	.0049 mg/L				
35	Room 114 Hand Sink East	MS-16	4/12/16	.0019 mg/L				
36	Room 113 Hand Sink West	MS-20	4/12/16	.0015 mg/L				
37	Room 113 Hand Sink Right	MS-19	4/12/16	.0028 mg/L				
38	Room 113 Hand Sink Left	MS-18	4/12/16	.0017 mg/L				
39	Room 113 Hand Sink North	MS-21	4/12/16	.0027 mg/L				
40	Room 116 Hand Sink North	MS2-40	9/27/16	.0067 mg/L				
41	Room 116 Island Hand Sink North	MS2-41	9/27/16	.0099 mg/L				
42	Room 116 Island Hand Sink South	MS2-42	9/27/16	.0027 mg/L				
43	Room 117 Island Hand Sink South	MS2-43	9/27/16	.0037 mg/L				
44	Room 117 Island Hand Sink North	MS2-44	9/27/16	.0026 mg/L				
45	Room 117 Hand Sink North	MS2-45	9/27/16	.0028 mg/L				
46	Board Room (small) Bath Hand Sink	MS2-46	9/27/16	.0045 mg/L				
47	Board Room (large) Bath Hand Sink	MS2-47	9/27/16	.0061 mg/L				
48	Board Room Hand Sink	MS-31	4/12/16	.0014 mg/L				
49	Special Needs Break Room Hand Sink	MS-30	4/12/16	.0011 mg/L				
50	District Office Bath Hand Sink	MS2-50	9/27/16	.012 mg/L				
51	Womens Bath Hand Sink	MS2-51	9/27/16	.0046 mg/L				
52	District Office Break Room Sink	MS-29	4/12/16	<.0010 mg/L				
53	Supt Office Bath Hand Sink	MS2-53	9/27/16	.0063 mg/L				
54	District Office Custodial Sink	MS2-54	9/27/16	.012 mg/L				
55	Nurses Office Bath Hand Sink South	MS2-55	9/27/16	.0029 mg/L				
56	Nurses Office Hand Sink	MS-28	4/12/16	.0012 mg/L				
57	Nurses Office Bath Hand Sink North	MS2-57	9/27/16	.0073 mg/L				
58	Main Office Bath Hand Sink	MS-27	4/12/16	<.0010 mg/L				
59	Library Hand Sink	MS-26	4/12/16	<.0010 mg/L				
60	Pod A Hall Water Fountain	MS-25	4/12/16	<.0010 mg/L				
61	Pod A Boys Bath Hand Sink Right	MS2-61	9/27/16	<.0010 mg/L				
62	Pod A Boys Bath Hand Sink Left	MS2-62	9/27/16	.0020 mg/L				
63	Pod A Girls Bath Hand Sink Left	MS2-63	9/27/16	<.0010 mg/L				
64	Pod A Girls Bath Hand Sink Right	MS2-64	9/27/16	<.0010 mg/L				
65	Pod A Custodial Sink	MS2-65	9/27/16	<.0010 mg/L				
66	Room 103 Bath Hand Sink	MS2-66	9/27/16	.0014 mg/L				
67	Room 103/104 Hand Sink	MS2-67	9/27/16	.0028 mg/L				
68	Science Hall Water Fountain	MS-24	4/12/16	<.0010 mg/L				
69	Room 137 Island Sink (Inside of Room)	MS2-69	9/27/16	.012 mg/L				
70	Room 137 Island Sink (Outside Wall)	MS2-70	9/27/16	.034 mg/L	Posted Non-Potable, Replace fixture, Retest			
71	Room 137 Island Sink (Inside of Room)	MS2-71	9/27/16	.051 mg/L	Posted Non-Potable, Replace fixture, Retest			
72	Room 137 Island Sink (Outside Wall)	MS2-72	9/27/16	.036 mg/L	Posted Non-Potable, Replace fixture, Retest			
73	Room 137 Island Sink (Inside of Room)	MS2-73	9/27/16	.016 mg/L	Posted Non-Potable, Replace fixture, Retest			
74	Room 137 Island Sink (Outside Wall)	MS2-74	9/27/16	.021 mg/L	Posted Non-Potable, Replace fixture, Retest			
75	Room 137 Island Sink (Inside of Room)	MS2-75	9/27/16	.014 mg/L				
76	Room 137 Island Sink (Outside Wall)	MS2-76	9/27/16	.022 mg/L	Posted Non-Potable, Replace fixture, Retest			
77	Room 137 Island Sink (Inside of Room)	MS2-77	9/27/16	.47 mg/L	Posted Non-Potable, Replace fixture, Retest			
78	Room 137 Island Sink (Outside Wall)	MS2-78	9/27/16	1.2 mg/L	Posted Non-Potable, Replace fixture, Retest			
79	Room 137 Island Sink (Inside of Room)	MS2-79	9/27/16	.012 mg/L				
80	Room 137 Island Sink (Outside Wall)	MS2-80	9/27/16	.077 mg/L	Posted Non-Potable, Replace fixture, Retest			
81	Room 137 Island Hand Sink (teacher)	MS2-81	9/27/16	.0092 mg/L				
82	Room 137/138 Storage Hand Sink	MS2-82	9/27/16	.010 mg/L				
83	Room 138 Island Hand Sink (teacher)	MS2-83	9/27/16	.0099 mg/L				
84	Room 138 Island Sink (Outside Wall)	MS2-84	9/27/16	.011 mg/L				
85	Room 138 Island Sink (Inside of Room)	MS2-85	9/27/16	.015 mg/L	Posted Non-Potable, Replace fixture, Retest			
86	Room 138 Island Sink (Outside Wall)	MS2-86	9/27/16	.012 mg/L				
87	Room 138 Island Sink (Inside of Room)	MS2-87	9/27/16	.012 mg/L				
88	Room 138 Island Sink (Inside of Room)	MS2-88	9/27/16	.022 mg/L	Posted Non-Potable, Replace fixture, Retest			
89	Room 138 Island Sink (Outside Wall)	MS2-89	9/27/16	.0094 mg/L				
90	Room 138 Island Sink (Inside of Room)	MS2-90	9/27/16	.0053 mg/L				
91	Room 138 Island Sink (Outside Wall)	MS2-91	9/27/16	.015 mg/L	Posted Non-Potable, Replace fixture, Retest			
92	Room 138 Island Sink (Inside of Room)	MS2-92	9/27/16	.0071 mg/L				
93	Room 138 Island Sink (Outside Wall)	MS2-93	9/27/16	.011 mg/L				
94	Room 138 Island Sink (Inside of Room)	MS2-94	9/27/16	.016 mg/L	Posted Non-Potable, Replace fixture, Retest			
95	Room 138 Island Sink (Outside Wall)	MS2-95	9/27/16	.38 mg/L	Posted Non-Potable, Replace fixture, Retest			
96	Greenhouse Hand Sink (Inside of Room)	MS2-96	9/27/16	.011 mg/L				
97	Greenhouse Hose Bib	MS2-97	9/27/16	.0026 mg/L				
98	Maintenance Break Hand Sink	MS-23	4/12/16	<.0010 mg/L				
99	Maintenance Bath Hand Sink	MS2-99	9/27/16	.0020 mg/L				
100	Pod B Hall Water Fountain	MS-22	4/12/16	<.0010 mg/L				
101	Pod B Girls Bath Hand Sink Left	MS2-101	9/27/16	.0030 mg/L				
102	Pod B Girls Bath Hand Sink Right	MS2-102	9/27/16	.0020 mg/L				
103	Pod B Boys Bath Hand Sink Right	MS2-103	9/27/16	.0060 mg/L				
104	Pod B Boys Bath Hand Sink Left	MS2-104	9/27/16	.0064 mg/L				
105	Pod B Custodial Sink	MS2-105	9/27/16	.0022 mg/L				
106	Room 111 Hand Sink	MS2-106	9/27/16	.0054 mg/L				
107	Room 111 Classroom Hand Sink	MS2-107	9/27/16	.0083 mg/L				
108	Room 112 Hand Sink	MS2-108	9/27/16	.0087 mg/L				
109	Pod C Outside Hose Bib	MS2-109	9/27/16	.0035 mg/L				
110	Room 212 Storage Hand Sink	MS2-110	9/27/16	.0018 mg/L				
111	Room 211 Storage Hand Sink	MS2-111	9/27/16	.0049 mg/L				
112	Pod B 2nd Floor Water Fountain	MS-34	4/12/16	<.0010 mg/L				
113	Pod B Boys Bath Hand Sink Right	MS2-113	9/27/16	<.0010 mg/L				
114	Pod B Boys Bath Hand Sink Left	MS2-114	9/27/16	.0014 mg/L				
115	Pod B Girls Bath Hand Sink Left	MS2-115	9/27/16	<.0010 mg/L				
116	Pod B Girls Bath Hand Sink Right	MS2-116	9/27/16	.0015 mg/L				
117	Pod B 2nd Floor Custodial Sink	MS2-117	9/27/16	.0018 mg/L				
118	Room 213 Hand Sink Left	MS2-118	9/27/16	.0078 mg/L				
119	Room 213 Hand Sink Right	MS2-119	9/27/16	.0040 mg/L				
120	Room 214 Hand Sink Right	MS2-120	9/27/16	.0080 mg/L				
121	Room 214 Hand Sink Left	MS2-121	9/27/16	.14 mg/L	Posted Non-Potable, Replace fixture, Retest			
122	61 Wing Water Fountain	MS-33	4/12/16	.0040 mg/L				
123	Faculty Bath Hand Sink	MS2-123	9/27/16	.0011 mg/L				
124	Faculty Break Room Hand Sink	MS-35	4/12/16	.0017 mg/L				
125	Room 225 Island Sink (Outside Wall)	MS2-125	9/27/16	.0065 mg/L				
126	Room 225 Island Sink (Inside of Room)	MS2-126	9/27/16	.012 mg/L				
127	Room 225 Island Sink (Outside Wall)	MS2-127	9/27/16	.0088 mg/L				
128	Room 225 Island Sink (Inside of Room)	MS2-128	9/27/16	.011 mg/L				
129	Room 225 Island Sink (Outside Wall)	MS2-129	9/27/16	.010 mg/L				
130	Room 225 Island Sink (Inside of Room)	MS2-130	9/27/16	.013 mg/L				
131	Room 225 Island Sink (Outside Wall)	MS2-131	9/27/16	.015 mg/L	Posted Non-Potable, Replace fixture, Retest			
132	Room 225 Island Sink (Inside of Room)	MS2-132	9/27/16	.014 mg/L				
133	Room 225 Island Sink (Outside Wall)	MS2-133	9/27/16	.0077 mg/L				
134	Room 225 Island Sink (Inside of Room)	MS2-134	9/27/16	.0099 mg/L				
135	Room 225 Island Sink (Outside Wall)	MS2-135	9/27/16	.0061 mg/L				
136	Room 225 Island Sink (Inside of Room)	MS2-136	9/27/16	.0089 mg/L				
137	Room 225 Hand Sink (teacher)	MS2-137	9/27/16	.018 mg/L	Posted Non-Potable, Replace fixture, Retest			
138	Room 225/224 Storage Hand Sink	MS2-138	9/27/16	.025 mg/L	Posted Non-Potable, Replace fixture, Retest			
139	Room 224 Hand Sink (teacher)	MS2-139	9/27/16	.023 mg/L	Posted Non-Potable, Replace fixture, Retest			
140	Room 224 Island Sink (Inside of Room)	MS2-140	9/27/16	.026 mg/L	Posted Non-Potable, Replace fixture, Retest			
141	Room 224 Island Sink (Outside Wall)	MS2-141	9/27/16	.054 mg/L	Posted Non-Potable, Replace fixture, Retest			
142	Room 224 Island Sink (Inside of Room)	MS2-142	9/27/16	.085 mg/L	Posted Non-Potable, Replace fixture, Retest			
143	Room 224 Island Sink (Outside Wall)	MS2-143	9/27/16	.045 mg/L	Posted Non-Potable, Replace fixture, Retest			
144	Room 224 Island Sink (Inside of Room)	MS2-144	9/27/16	.030 mg/L	Posted Non-Potable, Replace fixture, Retest			
145	Room 224 Island Sink (Outside Wall)	MS2-145	9/27/16	.021 mg/L	Posted Non-Potable, Replace fixture, Retest			
146	Room 224 Island Sink (Inside of Room)	MS2-146	9/27/16	.022 mg/L	Posted Non-Potable, Replace fixture, Retest			
147	Room 224 Island Sink (Outside Wall)	MS2-147	9/27/16	.022 mg/L	Posted Non-Potable, Replace fixture, Retest			
148	Room 224 Island Sink (Inside of Room)	MS2-148	9/27/16	.025 mg/L	Posted Non-Potable, Replace fixture, Retest			
149	Room 224 Island Sink (Outside Wall)	MS2-149	9/27/16	.022 mg/L	Posted Non-Potable, Replace fixture, Retest			
150	Room 224 Island Sink (Inside of Room)	MS2-150	9/27/16	.011 mg/L				
151	Room 224 Island Sink (Outside Wall)	MS2-151	9/27/16	.017 mg/L	Posted Non-Potable, Replace fixture, Retest			
152	2nd Floor Science Wing Water Fountain	MS-36	4/12/16	<.0010 mg/L				
153	Pod A 2nd Floor Water Fountain	MS-37	4/12/16	<.0010 mg/L				
154	Pod A Boys Bath Hand Sink Right	MS2-154	9/27/16	<.0010 mg/L				
155	Pod A Boys Bath Hand Sink Left	MS2-155	9/27/16	.0015 mg/L				
156	Pod A Girls Bath Hand Sink Left	MS2-156	9/27/16	<.0010 mg/L				
157	Pod A Girls Bath Hand Sink Right	MS2-157	9/27/16	.0019 mg/L				
158	Pod A 2nd Floor Custodial Sink	MS2-158	9/27/16	.0033 mg/L				
159	Room 204 Hand Sink Right	MS2-159	9/27/16	.0031 mg/L				
160	Room 204 Hand Sink Left	MS2-160	9/27/16	.0078 mg/L				
161	Room 203 Hand Sink Left	MS2-161	9/27/16	.013 mg/L				
162	Room 203 Hand Sink Right	MS2-162	9/27/16	.0025 mg/L				

High School

Location Number	Description	Sample #	Sample Date	Results	Remediation	Retest Sample #	Retest Date	Retest Results
1	Room 113 Hand Sink	HS2-1	10/25/2016	.0079 mg/L				
2	Receiving Hall Custodial Sink	HS2-2	10/25/2016	.083 mg/L	Posted Non-Potable, Replace fixture, Retest			
3	Room 114 South Island Sink West	HS2-3	10/25/2016	.010 mg/L				
4	Room 114 South Island Sink	HS2-4	10/25/2016	.015 mg/L	Posted Non-Potable, Replace fixture, Retest			
5	Room 114 South Island Sink	HS2-5	10/25/2016	.013 mg/L				
6	Room 114 South Island Sink East	HS2-6	10/25/2016	.013 mg/L				
7	Room 114 North Island Sink West	HS2-7	10/25/2016	.081 mg/L	Posted Non-Potable, Replace fixture, Retest			
8	Room 114 North Island Sink	HS2-8	10/25/2016	.015 mg/L	Posted Non-Potable, Replace fixture, Retest			
9	Room 114 North Island Sink	HS2-9	10/25/2016	.020 mg/L	Posted Non-Potable, Replace fixture, Retest			
10	Room 114 North Island Sink East	HS2-10	10/25/2016	.32mg/L	Posted Non-Potable, Replace fixture, Retest			
11	Room 114 Teacher Sink	HS2-11	10/25/2016	.027 mg/L	Posted Non-Potable, Replace fixture, Retest			
12	Room 114 South Sink	HS2-12	10/25/2016	.031 mg/L	Posted Non-Potable, Replace fixture, Retest			
13	Room 115 Northeast Wall Sink	HS2-13	10/25/2016	.0064 mg/L				
14	Room 115 Northwest Wall Sink	HS2-14	10/25/2016	.012 mg/L				
15	Room 115 Window Sink Right	HS2-15	10/25/2016	.0067 mg/L				
16	Room 115 Window Sink Center	HS2-16	10/25/2016	.022 mg/L	Posted Non-Potable, Replace fixture, Retest			
17	Room 115 Window Sink Left	HS2-17	10/25/2016	.076 mg/L	Posted Non-Potable, Replace fixture, Retest			
18	Room 115 Teacher Sink	HS2-18	10/25/2016	.024 mg/L	Posted Non-Potable, Replace fixture, Retest			
19	Room 115 Storage Sink	HS2-19	10/25/2016	.11 mg/L	Posted Non-Potable, Replace fixture, Retest			
20	Maintenance Break Room Sink	HS-5	4/11/2016	<.0010 mg/L				
21	Maintenance Bath Hand Sink	HS2-21	10/25/2016	<.0010 mg/L				
22	Faculty Mens Bath Hand Sink	HS2-22	10/25/2016	.0031 mg/L				
23	Faculty Womens Bath Hand Sink	HS2-23	10/25/2016	<.0010 mg/L				
24	Faculty Room Hand Sink	HS-6	4/11/2016	<.0010 mg/L				
25	Maintenance Hall Water Fountain	HS-7	4/11/2016	<.0010 mg/L				
26	Main Hall Custodial Sink	HS2-26	10/25/2016	<.0010 mg/L				
27	Girls Locker Hand Sink Left	HS2-27	10/25/2016	<.0010 mg/L				
28	Girls Locker Hand Sink Center	HS2-28	10/25/2016	<.0010 mg/L				
29	Girls Locker Hand Sink Right	HS2-29	10/25/2016	<.0010 mg/L				
30	Girls Locker Water Fountain	HS-18	4/11/2016	<.0010 mg/L				
31	PE Office Bath Hand Sink	HS2-31	10/25/2016	<.0010 mg/L				
32	Athletic Hall Custodial Sink	HS2-32	10/25/2016	.052 mg/L	Posted Non-Potable, Replace fixture, Retest			
33	Athletic Hall Water Fountain Right	HS-19	4/11/2016	<.0010 mg/L				
34	Athletic Hall Water Fountain Left	HS-20	4/11/2016	<.0010 mg/L				
35	Mens Bath Hand Sink Left	HS2-35	10/25/2016	<.0010 mg/L				
36	Mens Bath Hand Sink Center	HS2-36	10/25/2016	<.0010 mg/L				
37	Mens Bath Hand Sink Right	HS2-37	10/25/2016	<.0010 mg/L				
38	Womens Bath Hand Sink Right	HS2-38	10/25/2016	.0013 mg/L				
39	Womens Bath Hand Sink Center	HS2-39	10/25/2016	.0013 mg/L				
40	Womens Bath Hand Sink Left	HS2-40	10/25/2016	.0018 mg/L				
41	Concession Sink	HS-24	4/11/2016	.0042 mg/L				
42	Trainer Office Hand Sink	HS-23	4/11/2016	.0033 mg/L				
43	Trainer Office Ice Machine	HS2-43	10/25/2016	.015 mg/L	Posted Non-Potable, Replace fixture, Retest			
44	PE Office Bath Hand Sink Left	HS2-44	10/25/2016	<.0010 mg/L				
45	PE Office Bath Hand Sink Right	HS2-45	10/25/2016	.0011 mg/L				
46	Boys Locker Bath Hand Sink Left	HS2-46	10/25/2016	.0012 mg/L				
47	Boys Locker Bath Hand Sink Center	HS2-47	10/25/2016	<.0010 mg/L				
48	Boys Locker Bath Hand Sink Right	HS2-48	10/25/2016	<.0010 mg/L				
49	Boys Locker Water Fountain	HS-21	4/11/2016	<.0010 mg/L				
50	Boys Locker Team Room Water Fountain	HS-22	4/11/2016	<.0010 mg/L				
51	Room 117 Hand Sink	HS-17	4/11/2016	.0022 mg/L				
52	Room 117 Bath Hand Sink	HS2-52	10/25/2016	.0011 mg/L				
53	Foreign Language Hall Water Fountain	HS-16	4/11/2016	<.0010 mg/L				
54	Library Hall Custodial Sink	HS2-54	10/25/2016	.0032 mg/L				
55	Library Hall Womens Bath Hand Sink	HS2-55	10/25/2016	<.0010 mg/L				
56	Library Hall Mens Bath Hand Sink	HS2-56	10/25/2016	<.0010 mg/L				
57	Library Bath Hand Sink	HS2-57	10/25/2016	<.0010 mg/L				
58	Library Hand Sink	HS2-58	10/25/2016	<.0010 mg/L				
59	Library Hall Water Fountain	HS-15	4/11/2016	<.0010 mg/L				
60	Womens Bath Hand Sink Left	HS2-60	10/25/2016	<.0010 mg/L				
61	Womens Bath Hand Sink Right	HS2-61	10/25/2016	<.0010 mg/L				
62	Mens Bath Hand Sink Left	HS2-62	10/25/2016	<.0010 mg/L				
63	Mens Bath Hand Sink Right	HS2-63	10/25/2016	.0013 mg/L				
64	Senior Hall Water Fountain	HS-14	4/11/2016	.0017 mg/L				
65	Nurses Office Bath Hand Sink	HS2-65	10/25/2016	<.0010 mg/L				
66	Nurses Office Sink	HS-13	4/11/2016	<.0010 mg/L				
67	Principal Office Bath Hand Sink	HS2-67	10/25/2016	.0072 mg/L				
68	Womens Bath Hand Sink Left	HS2-68	10/25/2016	.0098 mg/L				
69	Womens Bath Hand Sink Center	HS2-69	10/25/2016	<.0010 mg/L				
70	Womens Bath Hand Sink Right	HS2-70	10/25/2016	.0011 mg/L				
71	Main Office Water Fountain Left	HS-12	4/11/2016	<.0010 mg/L				
72	Main Office Water Fountain Right	HS-11	4/11/2016	<.0010 mg/L				
73	Mens Bath Hand Sink Right	HS2-73	10/25/2016	.037 mg/L	Posted Non-Potable, Replace fixture, Retest			
74	Mens Bath Hand Sink Center	HS2-74	10/25/2016	.0030 mg/L				
75	Mens Bath Hand Sink Left	HS2-75	10/25/2016	.017 mg/L	Posted Non-Potable, Replace fixture, Retest			
76	Cafeteria Water Fountain Right	HS-10	4/11/2016	<.0010 mg/L				
77	Cafeteria Water Fountain Left	HS-9	4/11/2016	<.0010 mg/L				
78	Music Hall Water Fountain	HS-8	4/11/2016	<.0010 mg/L				
79	Music Womens Bath Hand Sink Left	HS2-79	10/25/2016	<.0010 mg/L				
80	Music Womens Bath Hand Sink Right	HS2-80	10/25/2016	<.0010 mg/L				
81	Music Mens Bath Hand Sink Right	HS2-81	10/25/2016	<.0010 mg/L				
82	Music Mens Bath Hand Sink Left	HS2-82	10/25/2016	<.0010 mg/L				
83	Music Storage Hand Sink	HS2-83	10/25/2016	.0059 mg/L				
84	Kitchen Ice Machine	HS2-84	10/25/2016	.027 mg/L	Posted Non-Potable, Replace fixture, Retest			
85	Kitchen Wash Sink Left	HS-3	4/11/2016	.0010 mg/L				
86	Kitchen Wash Sink Right	HS-4	4/11/2016	.0015 mg/L				
87	Kitchen Hand Sink	HS2-87	10/25/2016	.0013 mg/L				
88	Kitchen Island Sink	HS-2	4/11/2016	.0011 mg/L				
89	Kitchen Cook Water Supply	HS2-89	10/25/2016	.0015 mg/L				
90	Kitchen Wash Sink	HS-1	4/11/2016	0.0013 mg/L				
91	Kitchen Custodial Sink	HS2-91	10/25/2016	<.0010 mg/L				
92	Kitchen Bath Hand Sink	HS2-92	10/25/2016	<.0010 mg/L				
93	Room 232 Teacher Sink	HS2-93	10/25/2016	.037 mg/L	Posted Non-Potable, Replace fixture, Retest			
94	Room 232 Island Sink Out	HS2-94	10/25/2016	.16 mg/L	Posted Non-Potable, Replace fixture, Retest			
95	Room 232 Island Sink In	HS2-95	10/25/2016	.037 mg/L	Posted Non-Potable, Replace fixture, Retest			
96	Room 232 Island Sink Out	HS2-96	10/25/2016	.018 mg/L	Posted Non-Potable, Replace fixture, Retest			
97	Room 232 Island Sink In	HS2-97	10/25/2016	.25 mg/L	Posted Non-Potable, Replace fixture, Retest			
98	Room 232 Island Sink Out	HS2-98	10/25/2016	.020 mg/L	Posted Non-Potable, Replace fixture, Retest			
99	Room 232 Island Sink In	HS2-99	10/25/2016	.014 mg/L				
100	Room 232 Island Sink Out	HS2-100	10/25/2016	.0055 mg/L				
101	Room 232 Island Sink In	HS2-101	10/25/2016	.0055 mg/L				
102	Room 232 Island Sink In	HS2-102	10/25/2016	.038 mg/L	Posted Non-Potable, Replace fixture, Retest			
103	Room 232 Island Sink Out	HS2-103	10/25/2016	.031 mg/L	Posted Non-Potable, Replace fixture, Retest			
104	Room 232 Island Sink In	HS2-104	10/25/2016	.086 mg/L	Posted Non-Potable, Replace fixture, Retest			
105	Room 232 Island Sink Out	HS2-105	10/25/2016	.072 mg/L	Posted Non-Potable, Replace fixture, Retest			
106	Room 234 Teacher Sink	HS2-106	10/25/2016	.0070 mg/L				
107	Room 234 Island Sink Out	HS2-107	10/25/2016	.019 mg/L	Posted Non-Potable, Replace fixture, Retest			
108	Room 234 Island Sink In	HS2-108	10/25/2016	.031 mg/L	Posted Non-Potable, Replace fixture, Retest			
109	Room 234 Island Sink Out	Disconnected/Out of Service						
110	Room 234 Island Sink In	Disconnected/Out of Service						
111	Room 234 Island Sink Out	Disconnected/Out of Service						
112	Room 234 Island Sink In	Disconnected/Out of Service						
113	Room 234 Island Sink Out	Disconnected/Out of Service						
114	Room 234 Island Sink In	Disconnected/Out of Service						
115	Room 234 Island Sink Out	HS2-115	10/25/2016	.053 mg/L	Posted Non-Potable, Replace fixture, Retest			
116	Room 234 Island Sink In	HS2-116	10/25/2016	.036 mg/L	Posted Non-Potable, Replace fixture, Retest			
117	Room 234 Island Sink Out	HS2-117	10/25/2016	.061 mg/L	Posted Non-Potable, Replace fixture, Retest			
118	Room 234 Island Sink In	HS2-118	10/25/2016	.049 mg/L	Posted Non-Potable, Replace fixture, Retest			
119	Math Hall Water Fountain	HS-29	4/11/2016	<.0010 mg/L				
120	Art/Business Hall Water Fountain	HS-28	4/11/2016	<.0010 mg/L				
121	Art/Business Hall Custodial Sink	HS2-121	10/25/2016	.0050 mg/L				
122	Room 231 Island Sink Window	HS2-122	10/25/2016	.0028 mg/L				
123	Room 231 Island Sink Hall	HS2-123	10/25/2016	.0021 mg/L				
124	Room 233 Island Sink Window	HS2-124	10/25/2016	.0029 mg/L				
125	Room 233 Island Sink Hall	HS2-125	10/25/2016	<.0010 mg/L				
126	Room 233 Sink	HS2-126	10/25/2016	.0018 mg/L				
127	Dark Room Sink Right	HS2-127	10/25/2016	<.0010 mg/L				
128	Dark Room Sink Center	HS2-128	10/25/2016	.0052 mg/L				
129	Dark Room Sink Left	HS2-129	10/25/2016	.0048 mg/L				
130	Sophomore Hall Water Fountain	HS-27	4/11/2016	<.0010 mg/L				
131	2nd Floor Girls Bath Hand Sink Left	HS2-131	10/25/2016	.0076 mg/L				
132	2nd Floor Girls Bath Hand Sink Center	HS2-132	10/25/2016	.0055 mg/L				
133	2nd Floor Girls Bath Hand Sink Right	HS2-133	10/25/2016	.0033 mg/L				
134	2nd Floor Bath Water Fountain Left	HS-26	4/11/2016	<.0010 mg/L				
135	2nd Floor Bath Water Fountain Right	HS-25	4/11/2016	.0011 mg/L				
136	2nd Floor Boys Bath Hand Sink Right	HS2-136	10/25/2016	.0015 mg/L				
137	2nd Floor Boys Bath Hand Sink Center	HS2-137	10/25/2016	.0036 mg/L				
138	2nd Floor Boys Bath Hand Sink Left	HS2-138	10/25/2016	.0014 mg/L				
139	2nd Floor Womens Faculty Bath Sink	HS2-139	10/25/2016	.0012 mg/L				
140	2nd Floor Mens Faculty Bath Sink	HS2-140	10/25/2016	<.0010 mg/L				
141	2nd Floor Music Hall Water Fountain	HS-30	4/11/2016	<.0010 mg/L				
142	Room 213 Teacher Sink	HS2-142	10/25/2016	.016 mg/L	Posted Non-Potable, Replace fixture, Retest			
143	Room 213 East Hand Sink	HS2-143	10/25/2016	.0066 mg/L				
144	Room 213 Island Sink East	HS2-144	10/25/2016	.017 mg/L	Posted Non-Potable, Replace fixture, Retest			
145	Room 213 Island Sink West	HS2-145	10/25/2016	.0091 mg/L				
146	Room 213 West Sink Right	HS2-146	10/25/2016	.0043 mg/L				
147	Room 213 West Sink Left	HS2-147	10/25/2016	.013 mg/L				
148	Room 213/211 South Sink	HS2-148	10/25/2016	.18 mg/L	Posted Non-Potable, Replace fixture, Retest			
149	Room 213/211 East Sink	HS2-149	10/25/2016	.034 mg/L	Posted Non-Potable, Replace fixture, Retest			
150	Room 211 East Sink Right	HS2-150	10/25/2016	.0098 mg/L				
151	Room 211 East Sink Left	HS2-151	10/25/2016	.0053 mg/L				
152	Room 211 Island Sink East	HS2-152	10/25/2016	.13 mg/L	Posted Non-Potable, Replace fixture, Retest			
153	Room 211 Island Sink West	HS2-153	10/25/2016	.020 mg/L	Posted Non-Potable, Replace fixture, Retest			
154	Room 211 West Sink	HS2-154	10/25/2016	.040 mg/L	Posted Non-Potable, Replace fixture, Retest			
155	Room 211 Teacher Sink	HS2-155	10/25/2016	.83 mg/L	Posted Non-Potable, Replace fixture, Retest			
156	Technology Hall Water Fountain	HS-31	4/11/2016	.0013 mg/L				
157	Room 214 Teacher Sink	HS2-157	10/25/2016	<.0010 mg/L				
158	Room 214 Window Sink Left	HS2-158	10/25/2016	<.0010 mg/L				
159	Room 214 Window Sink Left/Center	HS2-159	10/25/2					

Lake Street

<u>Location Number</u>	<u>Description</u>	<u>Sample #</u>	<u>Sample Date</u>	<u>Results</u>	<u>Remediation</u>	<u>Retest Sample #</u>	<u>Retest Date</u>	<u>Retest Results</u>
1	Gym Hall Water Fountain Left	LS-3	5/4/2016	.0012 mg/L				
2	Gym Hall Water Fountain Right	LS-4	5/4/2016	.0014 mg/L				
3	Boys Gang Bath Hand Sink Left	LS2-3	10/25/2016	.0048 mg/L				
4	Boys Gang Bath Hand Sink Center	LS2-4	10/25/2016	.0020 mg/L				
5	Boys Gang Bath Hand Sink Right	LS2-5	10/25/2016	.0038 mg/L				
6	Girls Gang Bath Hand Sink Left	LS2-6	10/25/2016	.0092 mg/L				
7	Girls Gang Bath Hand Sink Center	LS2-7	10/25/2016	.0056 mg/L				
8	Girls Gang Bath Hand Sink Right	LS2-8	10/25/2016	.0032 mg/L				
9	Boys Locker Water Fountain	LS-1	5/4/2016	.0091 mg/L	Disconnected power and water supply to fountain. No longer in service.			
10	Boys Locker Bath Hand Sink Right	LS2-10	10/25/2016	.0079 mg/L				
11	Boys Locker Bath Hand Sink Left	LS2-11	10/25/2016	.018 mg/L	Posted Non-Potable, Replace fixture, Retest			
12	Girls Locker Water Fountain	LS-2	5/4/2016	.018 mg/L	Disconnected power and water supply to fountain. No longer in service.			
13	Girls Locker Bath Hand Sink	LS2-13	10/25/2016	.036 mg/L	Posted Non-Potable, Replace fixture, Retest			

Transportation

<u>Location Number</u>	<u>Description</u>	<u>Sample #</u>	<u>Sample Date</u>	<u>Results</u>	<u>Remediation</u>	<u>Retest Sample #</u>	<u>Retest Date</u>	<u>Retest Results</u>
1	Hall Water Fountain Right	BG-1	5/4/2016	<.0010 mg/L				
2	Hall Water Fountain Left	BG-2	5/4/2016	<.0010 mg/L				
3	Drive Break Room Hand Sink	BG-3	5/4/2016	<.0010 mg/L				
4	Mechanic Break Room Hand Sink	BG-4	5/4/2016	<.0010 mg/L				

Maintenance

<u>Location Number</u>	<u>Description</u>	<u>Sample #</u>	<u>Sample Date</u>	<u>Results</u>	<u>Remediation</u>	<u>Retest Sample #</u>	<u>Retest Date</u>	<u>Retest Results</u>
1	First Floor Break Room Hand Sink	MT-1	5/4/2016	<.0010 mg/L				
2	Water Fountain	MT-2	5/4/2016	<.0010 mg/L				